

BMW Group - AIR: 2026-07-29 / 14:13
Retailer: 32711/06
Model: X5 xDrive50e
Vehicle identification number: 5UX43EU09R9S66365
Development code: G05
Model code: 43EU
Lead type: 43EU

Vehicle

BMW X5 xDrive50e, 360KW
5UX43EU09R9S66365



Development code	G05
Colour	mineral-weiss metallic
Actual integration level	S18A-25-07-551
Start of warranty	31 May 2023

Technical campaigns

There are no Campaigns for this vehicle.

Special information

There are no Campaigns for this vehicle.

Live Diagnosis

 There are no service solutions for Live Diagnosis.

Service contracts

No BSI contracts

Information on faults workshop/Service Consultation

There is no information on faults.

Navigation map

Note: The installed map could not be detected.

Note: No free installable maps are available for this vehicle.

Vehicle details

Vehicle type	Passenger car
Brand	BMW

Model	X5 xDrive50e
Body	GEFZG
Vehicle identification number (last 7 digits)	9S66365
Vehicle identification number (17 digits)	5UX43EU09R9S66365
Development code	G05
Steering	LL
Engine	XB1N
Engine number	19847111
Exhaust re-treatment	No information
Transmission	AUT
Transmission number	0007928WSQ
Head unit serial number	No head unit could be found.
Drive	ALLR
Integration level, works	S18A-23-03-545
Production date	21 May 2023
Production plant	Spartanburg
Delivery date	25 May 2023
Delivering retailer	Sharpe BMW, Grand Rapids, US
National-market version	USA
Paint code	A96
Upholstery code	VASW
Model code	43EU
Basic type	43EU
Lead type	43EU

Optional equipment

Optional equipment ex works:

01CB CO2 equipment
 01DR Exhaust emission standards SULEV30
 01TD 20" light-al.whl. star spoke 740M em.op.
 0212 National brake system equipment
 0258 Tyres with runflat properties
 02TB Sport automatic gearbox
 02VB Tyre pressure display
 02VR Two-axle air suspension
 0302 Alarm system
 0319 Integrated universal remote control
 0322 Comfort access system
 0337 M Sports package
 03AC Trailer coupling
 03DZ Omission of additional lettering, outer
 03MC M roofrailing, Shadow Line
 0402 Panorama glass roof
 0420 Sun protection glazing
 0423 Floor mats velours
 0453 Climate-controlled seats, front
 0456 Comfort seat with memory

Retrofitted optional equipment:

This vehicle has no retrofits.

04FL Travel & Comfort rail system
04HA Seat heating, front and rear
04HB Heat comfort package, front
04KR Fine-wood trim Finline Stripe
04NB Autom. climate control with 4-zone ctrl
04T3 Flexible Charger (Mode 2)
04T8 Extended mirror package
04U9 Acoustic pedestrian protection
04UR Ambient interior light
04V1 BMW ICONICSOUNDS ELECTRIC
0552 Adaptive LED headlight
05AC High-beam assistant
05AL Active Protection
05AP Decoding anti-glare high-beam assistant
05AU Driving assistant professional
05AX Motorway assistant
05DW Parking Assistant Professional
0645 BMW US Radio
0655 Satellite tuner
0688 Harman/Kardon surround sound system
06AC Intelligent emergency call
06AE Teleservices
06AK Connected Drive Services
06C4 Connected Package Professional
06CP Smartphone integration
06NX Storage tray wireless charging
06PA Personal eSIM
06U3 BMW Live operating area Professional
06U8 BMW gesture control
0710 M leather steering wheel
0715 M Aerodynamics package
0760 High gloss shadow line
0775 Headlining anthracite
0823 Hot-climate version
0842 Cold-climate version
0845 Acoustic fasten seat belt reminder
0853 Language version, English
08BK Charging socket Export
08KL Oil service interval 15,000 km/12 months
08R9 Refrigerant R1234yf
08SM Car ident. number visible from outside
08TN Daytime driv.lights adjus.via light menu
08TT DECODING ADDITIONAL FUNCTIONS II
0992 Control of number-plate attachment
A080 80 Ah AGM battery

Control unit software version

Vehicle histories

	Date	Type	Vehicle mileage	Retailer	Overview
—	30/07/2025	Key	68519 Km	86862	Key 0
					
	1040	1040		1040	1040
	01/2026	01/2026		01/2026	01/2026
—	30/07/2025	Repair	68547 Km	86862 ,	Job Job Job Job
—	Job				
	Description:				
	Considered as a repeat visit	No			

Customer's own words BMW OIL CHANGE

unknown fru: BMW OIL CHANGE Flat rate unit I 01BMZOF	Local	5 FRU
Set oil-filter element Part I 11 42 7 826 799		1
unknown part: BMW GROUP LL-22FE++ Part I 83215B72B17	Local	70

— Job

Description:

Considered as a repeat visit No

Customer's own words MICROFILTER

MICROFILTER Flat rate unit I 01BMZMI	Local	8 FRU
Set, microfilter/carbon canister Part I 64115A1BDB6		1

— Job

Description:

Considered as a repeat visit No

Customer's own words BMW AIR FILTER

AIR FILTER Flat rate unit I 01BMZAI	Local	2 FRU
Air filter insert Part I 13715A24FB2		1

— Job

Description:

Considered as a repeat visit No

Customer's own words PERFORM VIDEO INSPECTION OF THE VEHICLE

unknown fru: VIDEO INSPECTION Flat rate unit I 88BMZ02	Local	0 FRU
---	-------	-------

— 20/05/2025 Key 61284 Km 86862 Key 0

 8270 01/2026	 8270 01/2026	 8270 01/2026	 8270 01/2026	 8270 01/2026	 8270 05/2026	 8270 01/2026	 8270 01/2026
--	--	--	--	--	--	--	---

— 20/05/2025 Repair 61309 Km 86862 , Job Job

— Job

Description:

Considered as a repeat visit No

Customer's own words LOANER CAR

LOANER CAR Flat rate unit I -	Local	0 FRU
----------------------------------	-------	-------

— Job

Description:

Considered as a repeat visit No

Customer's own words PERFORM VIDEO INSPECTION OF THE VEHICLE

unknown fru: VIDEO INSPECTION Local 0 FRU
Flat rate unit I 88BMZ02

16/01/2025 Key 51949 Km 86862 Key 0



16/01/2025 Repair 51971 Km 86862 , Job
Job

Job

Description:

Considered as a repeat visit No

Customer's own words PERFORM VIDEO INSPECTION OF THE VEHICLE

unknown fru: VIDEO INSPECTION Local 0 FRU
Flat rate unit I 88BMZ02

Job

Description:

Considered as a repeat visit No

Customer's own words CUSTOMER REQUEST ROTATION OF TIRES

BMW ROTATE TIRES Local 3 FRU
Flat rate unit I 01BMZRO

03/01/2025 Key 50923 Km 06862 Remote KeyRead



16/12/2024 Key 49640 Km 06862 Remote KeyRead



16/12/2024 Key 49640 Km 06862 Remote KeyRead



07/12/2024 Key 48920 Km 06862 Remote KeyRead



1980
06/2025











05/2026





19980
06/2026

—

17/06/2024

Key

33289 Km

86862

Key 0



1680
12/2024







1680
12/2024





05/2026





37680
12/2026

—

17/06/2024

Repair

33303 Km

86862 ,

Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words LOANER CAR

LOANER CAR

Flat rate unit | -

Local

0 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words PERFORM VIDEO INSPECTION OF THE VEHICLE

unknown fru: VIDEO INSPECTION

Flat rate unit | 88BMZ02

Local

0 FRU

—

13/12/2023

Key

17364 Km

86862

Key 0



260
05/2024











05/2026





54260
05/2027

—

13/12/2023

Repair

17370 Km

86862 Sharpe
BMW/MINI of
Grand Rapids ,
Grand Rapids

Job

— Job

Description:

Considered as a repeat visit No

Customer's own words PERFORM VIDEO INSPECTION OF THE VEHICLE

!!! unknown BMW-Id 88BMZ02 VIDEO INSPECTION !!!

Flat rate unit | 88BMZ02

Local

0 FRU

—

31/05/2023

Repair

18 Km

86862 Sharpe
BMW/MINI of
Grand Rapids ,
Grand Rapids

Job

— Job

Description:

Considered as a repeat visit No

Customer's own words INTERNAL ONLY-SOLD VEHICLE SEDAN-2.5 SUV-3.

WASH WAX AND DETAIL	Local	0 FRU
Flat rate unit -		

—	30/05/2023	Key	17 Km	Key 10
---	------------	-----	-------	--------

—	30/05/2023	Repair	18 Km	86862 Sharpe BMW/MINI of Grand Rapids , Grand Rapids	Job Job
---	------------	--------	-------	---	------------

— Job

Description:

Considered as a repeat visit No

Customer's own words

LOANER CAR EXPENSE	Local	0 FRU
Flat rate unit 26BMZLO		

— Job

Description:

Considered as a repeat visit No

Customer's own words AFTER PDI CHARGE VEHICLE TO 100% STATE OF CHARGE.

CHARGE VEHICLE	Local	0 FRU
Flat rate unit 26BMZCH		

—	26/05/2023	Key	14 Km	Key 10
---	------------	-----	-------	--------